

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / TECH/ W.F. 13-Oct-2024/2024-25/172

dated:01/11/24

Name of the Work: Improvement and Covering of nallah behind Crisville CHSL to Telis house at Aquem Alto in Margao Constituency.

Sample Sent by: Assistant Engineer, SD III, WD III, WRD, Gogol- Margao -Goa

Letter No: No. 342/SDIII/ WD III/WRD/24-25/243

Dated:- 30-10-2024

Received on: 30-10-2024

Date of Testing 1/11/2024

REPORT

Sr No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F. 13/01/2024	Coarse Sand	FM Silt & Clay Grading	2.374 1.90% Zone III	2.3 to 3.1 Upto 5% I to III Zone	
F. 13/02/2024	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion.
F. 13/03/2024	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD III, WD III , WRD, Gogol- Margao-Goa.
- 2) Executive Engineer, WD XI, WRD,Rawanfond-Goa.
- 3) Executive Engineer, WD III, WRD, Ponda -Goa.
- 4) The Surveyor of Works,Quality Control, C.P.O., Water Resources Dept., Sinchai Bhavan,Alto Porvorim-Goa.
- 5) Office File.