

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / TECH / WF. 86 -Oct-2022 / 65 /2023-24.

Dated:24/04/2023

Name of the Work: Improvement of Drain near Niclao house at Aquem Baixo in Margao Constituency.

Sample Sent by: Assistant Engineer , SD III , WD III , WRD , Gogol- Margao - Goa.

Letter No: 323/SD III/ WD III/WRD/222-23/29.

Dated:- 21-04-2023

Received on: 21-04-2023

Date of Testing 24-04-2023

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F.86/01/2022	Metal Sand	FM Silt & Clay Grading	2.988 2.00% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
F. 86/02/2022	Aggregate-20 mm	Grading		As per IS-383:2016	To get the 20mm graded aggregate nominal size blend
F. 86/03/2022	Aggregate- 10 mm	Grading		As per IS-383:2016	20mm & 10 mm metal in 1:1 proportion.

Junior Engineer

Assistant Engineer

- Copy submitted to
- 1) Assistant Engineer, SD III, WD III, WRD, Gogol- Margao- Goa.
 - 2) The Executive Engineer, Works Division III, WRD, Ponda- Goa.
 - 3) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
 - 4) The Surveyor of Works,Quality Control, C.P.O.,Water Resources Dept., Sinchai Bhavan,Alto Porvorim-Goa.
 - 5) Office File.