## GOVERNMENT OF GOA OFFICE OF THE ASSISTANT ENGINEER SUB DIVISION III WORKS DIVISION XI QUALITY CONTROL LABORATORY (SOUTH), WATER RESOURCES DEPARTMENT, GOGAL, MARGAO- GOA.

## PLEASE FIND THE TEST RESULTS OF CEMENT AS DETAILED BELOW:

**Name of work**:- Improvement and Covering of existing nallah near Lala house at Aquem Margao- Goa.

Type of Cement: Ordinary Portland cement Brand / Grade: Ultra tech/43 grade

Source of receipt: Assistant Engineer, SD III, WD III, WRD, Gogol- Margao Goa.

**Ref.** Letter No: 287/SD III/ WD III/ WRD/2021-22/307. **Dated:** 09-11-2021.

**Qty. Represented:** 

**L.S. No:** F.42/04/2021.

**Physical Properties** 

Sr.	Description	Test results	Requirements as per I.S.
No			
1	Fineness. (% retained on 9		Not more than 10%
	micron sieve)	4%	
2	Setting Time in (Minutes)		
	i) Initial	178minutes	Not less than 30 Min
	ii) Final.	272minutes	Not more than 600 Min.
3	Minimum Com Strength Kg/Cm <sup>2</sup>		
	i) 72 hrs. ±1 hrs.	346.66Kg/cm2	Not less than 230.0 Kg/cm2
	ii) 168 hrs. ±2 hrs	433.33Kg/cm2	Not less than 330.0Kg/cm2
	iii) 672 hrs. ±4 hrs	546.66Kg/cm2	Not less than 430.0Kg/cm2
4	Consistency of cement.	29%	

To.

The Asst. Engineer.SD III, WD III, WRD, Gogol- Margao- Goa.

C.W.C. Submitted to:

- 2. The Exe. Eng. W.D. XI, WRD, Rawanfond-Goa.
- 3. Office file.

**Junior Engineer** 

Assistant Engineer.