

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
 S.D.III. (C.P.O) QUALITY CONTROL LABORATORY
 GOGAL, MARGAO- GOA

NO: WRD /WD XI / SD III/ F.59/W.F. 34/2020 / 214 / 2020-21		Dated: 15-02-2021	
Name of the Work :- Improvement to Colva creek and Construction of retaining wall wherever necessary between Sy. No. 20, 27 and Sy. No. 23 in Colva			
Village in Benaulim Constituency.			
REQUISITION DETAILS: NO: WRD / SD I/ WD II/F. Esst / 821/ 2020-21.		Dated:-11-02-2021	
SAMPLE SENT BY: Assistant Engineer, Sub. Div. I, Works Div. II, WRD, Rawanfond- Goa.			
SAMPLE RECEIVED ON: 11/2/2021			
TYPE OF SAMPLE: Latrite boulders			
STRENGTH REQUIRED:			
TESTING DATE: 15-02-2021			
TESTED BY: Junior Engineer		AUTHORISED BY: AE, SD III, QC.	
AGENCY NAME:			
Sr. No:	SAMPLE NUMBER	Comp. strength in Kg/sq.cm.	AVERAGE Kg/sq.cm
1	167	39.74	40.39
2	168	39.74	
3	169	42.78	
4	170	38.02	
5	171	41.67	

Junior Engineer

Assistant Engineer

To,
 Assistant Engineer, Sub- Div. I, Works Div.II, WRD, Rawanfond- Goa.

Copy Submitted To:

1. Executive Engineer, Works Div. XI, WRD, Rawanfond-Goa .
2. Office File No: F-59