

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59 /WF.88 / 2021/ 47 / 2021-22. dated: 14/06/21

Name of the Work: Beautification of main Dome and Shilp work of Mahalxmi Temple at Vaddem Rehabilitation Site.

Sample Sent by: Assistant Engineer, SD IV , WD X, WRD, Pajimol, Sanguem-Goa

Letter No: WRD / WD X/SD IV /W. F.60 / 25 / 2021-22.

Dated:- 9/6/2021

Received on: 10/6/2021

Date of Testing: 14-06-2021

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
462/2021	Coarse Sand	FM Silt & Clay Grading	2.926 3.20% II	2.3 to 3.1 Upto 5% I to III Zone	
463/2021	Fine Sand	FM Silt & Clay Grading	1.988 2.60% IV	< 2.3 Upto 5% Zone IV	
464/2021	Aggregate-20 mm	Grading		As per IS-383:2016	To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion.
465/2021	Aggregate- 10 mm	Grading		As per IS-383:2016	

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD IV, WD X , WRD, Pajimol, Sanguem-Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) The Executive Engineer, Works Division X, WRD, Pajimol, Sanguem- Goa.
- 4) Office File.