

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59 / WF.92 /2021/67 / 2021-22.

dated: 07/07/2021

Name of the Work: Improvement to drain at Soshebhat in V.P. Durbhat in Ponda Taluka.

Sample Sent by :- Assistant Engineer, SD IV, WD XI, WRD, Ponda - Goa.

Letter no:- No. WRD/WD XI/SD IV/W.F.483/153/2021-22.

Dated:- 5/7/2021

Received on: 5/7/2021

Date of Testing: 07-07-2021

REPORT

| Sample No. | Type of Sample | Tested for | Result | Permissible value | REMARKS |
|------------|------------------|------------------------------|---------------------------|--|---|
| 497/2021 | Coarse Sand | FM Silt & Clay Grading | 2.894 2.20% Zone II | 2.3 to 3.1 Upto 5% I to III Zone | |
| 498/2021 | Aggregate-20 mm | Grading | | As per IS-383:2016 | To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion. |
| 499/2021 | Aggregate- 10 mm | Grading | | As per IS-383:2016 | |

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD IV, WD XI, WRD, Ponda-Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) Office File.

