

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59/ W.F. 126/2021 /06 / 2022-23.

dated:- 11/04/2022

Name of the Work: Improvement of outlet of Pond in Sy.No.17/17 in Village Sirlim in Velim Constituency.

Sample Sent by :- Assistant Engineer, SD I, WD II , WRD, Rawanfond - Goa.

Letter no:- No. WRD/SD I/WD II/F.Esst/03/2022-23.

Dated:- 01-04-2022.

Received On: 01-04-2022

Date of Tesing: 04-04-2022

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F.126/1/2021	Coarse Sand	FM Silt & Clay Grading	2.618 1.60% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
F.126/2/2021	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the 20mm graded aggregate nominal size blend
F.126/3/2021	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	20mm & 10 mm metal in 1:1 proportion.

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD I, WD II , WRD, Rawanfond-Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) The Executive Engineer, Works Division II, WRD, Rawanfond- Goa.
- 4) Office File.