

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59/W.F. 23/2021 /137 / 2021-22 .

dated: 17/11/2021

Name of the Work: Protection wall for nallah in Sy.No. 130/23 to Sy.No. 130/39 in Village Mullem in Cuncolim Constituency.

Sample Sent by: Assistant Engineer, SD I, WD II, WRD, Rawanfond-Goa

Letter No: No. WRD/SD I/ WD II/F.Esst/519/2021-22.

Dated:- 1/11/2021

Received On: 05-11-2021

Date of Testing: 09-11-2021

REPORT

Sr No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
F.23/01/2021	Coarse Sand	FM Silt & Clay Grading	2.946 2.00% Zone- II	2.3 to 3.1 Upto 5% I to III Zone	
F.23/02/2021	Aggregate-20 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	To get the 20mm graded aggregate nominal size blend
F.23/03/2021	Aggregate- 10 mm	Grading		As per IS-383-1970 (Re-affirmed in 1990)	20mm & 10 mm metal in 1:1 proportion.

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD I, WD II, WRD, Rawanfond-Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) Executive Engineer, WD II, WRD, Rawanfond-Goa.
- 4) Office File.