

GOVERNMENT OF GOA
WATER RESOURCES DEPARTMENT
S.D.III., Works Div. XI, QUALITY CONTROL LABORATORY
Gogol - Margao - Goa.

No. WRD / WD XI / SDIII / F.59 / WF.33/2021 / **222** / 2020-21.

dated: 15-02-2021

Name of the Work: Urgent Repairs to existing spring & Tank at Daab Shirshirem in V.P. Borim of Shiroda Constituency. (2nd call).

Sample Sent by: Assistant Engineer, SD IV, WD XI, WRD, Ponda-Goa

Letter No: No.WRD/WD XI/SD IV/W.F.374/114/2020-21

Dated:- 11/2/2021

Received on: 11/2/2021

Date of Testing: 15-02-2021

REPORT

Sample No.	Type of Sample	Tested for	Result	Permissible value	REMARKS
154/2021	Coarse Sand	FM Silt & Clay Grading	2.606 1.40% Zone II	2.3 to 3.1 Upto 5% I to III Zone	
155/2021	Aggregate-20 mm	Grading		As per IS-383:2016	To get the 20mm graded aggregate nominal size blend 20mm & 10 mm metal in 1:1 proportion.
156/2021	Aggregate- 10 mm	Grading		As per IS-383:2016	

Junior Engineer

Assistant Engineer

Copy submitted to

- 1) Assistant Engineer, SD IV, WD XI, WRD, Ponda-Goa.
- 2) The Executive Engineer, Works Division XI, WRD, Rawanfond- Goa.
- 3) Office File.