

GOVERNMENT OF GOA
QUALITY CONTROL LABORATORY
WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T : 1096/ Lab / **257**/ 2020 - 21 Dated:- 22/ 02 / 2021. Laboratory : Bicholim - Goa.
Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of work :Construction of Kamurlim branch from ch.4.61km to ch.5.320km and OL-5 and OT and its field network of LBMC of TIP village Kamurlim in Bardez Taluka.

Ref. to Requisition No.: SDI/WDVIII/WRD/WF-34/2020-21/211 Dated :- 19/ 02/ 2021.

Qty. Recived. :01 Sets of cube Date of Receipt:- 19/02/ 2021. Tested on: -22/02/2021as per due dates. Ref to CPWD :2009, Vol. I

Sample: Cube Mix 1:2:4 O.S No. : 5162/ SS . Lab. Sample No.:511 Tested By: Mrs. S.B. Naik Shirodkar. J.E.

REPORT PAGE 01 OF 01

SR. NO.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissible	% above or below	REMARK
1	Cement concrete cube of mix 1:2:4 , cast on 15/02/2021.P.C.C for beds & Chamber.	7 th day compressive strength	144.98	Kg/Cm ²	140.00 Kg/cm ²	6.25	1)Qty represents -6.00 Cum. 2)28th day test due on 15/03/2021
			147.24	Kg/Cm ²			
			154.04	Kg/Cm ²			
		Average	148.75	Kg/Cm²			

Copy to: 1. The Assistant Engineer , SD I , WD VIII,WRD, Karaswada-Bardez - Goa.

2. Copy submitted to The Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.

3. Copy submitted to The Executive Engineer , WD VIII,WRD, Karaswada-Bardez - Goa.

4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer