

**GOVERNMENT OF GOA
QUALITY CONTROL LABORATORY
WATER RESOURCES DEPARTMENT**

Test Report No.: WRD / QC / F.6-2 / Cube -T : 7648/ Lab / **229** / 2019 - 20

Dated:- 05/ 07 / 2019 Laboratory : Bicholim - Goa.

Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of Work: - Construction of Irrigation well in the field of Shri. Pramod G. Gawade at Melauli at Survey No. 39/7, V.P. Guleli in Sattari Taluka.

Ref. to Requisition no.: MI/WDVI/WRD/SDII/ F.62/120 /2019-20 dated :-10/06/2019.

Qty. Recived. : 01 Set of cube

Date of Receipt: 12/06/2019.

Tested on: 05/07/2019.

Ref to CPWD :2002, Vol. I

Sample: Cube 1:2:4 Mix O.S No. :1028/AF Lab. Sample No.:6101 Tested By: Mr. Anil R. Fadte, J.E.

REPORT PAGE 01 OF 01

SR.N O.	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissible	% above or below	REMARK
1	Plain Cement concrete cube of mix 1:2:4 , cast on 07/06/2019, for well ring from bottom to 3.00 mt. height.	28 th day compressive strength	242.38	Kg/Cm2	210 kg/cm2	11.11	Quantity represents 10.00 Cum.
			226.53	Kg/Cm2			
			231.06	Kg/Cm2			
		Average	233.32	Kg/Cm2			

1. Copy to: The Assistant Engineer ,SD II,WD VI,WRD, Valpoi-Sattari-Goa.
2. Copy submitted to:The Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.
3. Copy submitted to:The Executive Engineer ,WDVI,WRD, Bicholim Goa.
4. QC Lab File.
5. Bill File.

Junior Engineer

Assistant Engineer