GOVERNMENT OF GOA QUALITY CONTROL LABORATORY WATER RESOURCES DEPARTMENT

Test Report No.: WRD / QC / F.6-2 / Cube -T : 2813,2820/ Lab / **222**/ 2021 - 22 Dated: - 04/12/2021. Laboratory : Bicholim - Goa.

Sub Division V (QC)/WRD/ Bicholim- Goa.

Name of work: Construction of road side drain from CADA garage to old water sumps at T.I.P Complex Karaswada Bardez Goa.

Ref. to Requisition No.: SDIII/WDVIII/WRD/W.F.75/2021-22/223 Dated :- 26/11/2021.

Qty. Recived. :02 Sets of cube Date of Receipt:- 30/11/2021. Tested on: -30/11/2021 & 03/12/2021 as per due dates. Ref to CPWD :2009, Vol. I

Sample: Cube Mix 1:2:4 O.S No.: 7141 &7156/ SS. Lab. Sample No.: 2441 To 2442 Tested By: Mrs. S.B. Naik Shirodkar. J.E.

REPORT PAGE 01 OF 01

SR NO	DISCRIPTION OF SAMPLE	TESTED FOR	RESULTS		Max./Min.Value permissable	% above or below	REMARK
1	Cement concrete cube of mix 1:2:4, cast on 02/11/2021. For P.C.C for Drain	28th day	237.85	Kg/Cm ²	210.00 Kg/cm ²	10.75	1) Qty represents -14.00 Cum.
		compressive	226.53	Kg/Cm ²			
		strength	233.32	Kg/Cm ²			
		Average	232.57	Kg/Cm ²			
2	Cement concrete cube of mix 1:2:4, cast on 05/11/2021. For Both side drain walls	28th day	226.53	Kg/Cm ²	210.00 Kg/cm ²	3.91	1) Qty represents -16.00 Cum.
		compressive	217.47	Kg/Cm ²			
		strength	210.67	Kg/Cm ²			
		Average	218.22	Kg/Cm ²			

Copy to: 1. The Assistant Engineer , SD III , WD VIII, WRD, Karaswada-Bardez - Goa.

- 2. Copy submitted to The Superintending Engineer ,CPO,WRD, Sinchai Bhavan, Porvorim Goa for kind Information.
- 3. Copy submitted to The Executive Engineer, WD VIII, WRD, Karaswada-Bardez Goa.
- 4. QC Lab File. 5. Bill File.

Junior Engineer

Assistant Engineer